2408

Bearing East 5 Miles

Bearing North 4 6° East 3 Miles 62 Chains

Road to Hill Station

Bearing North 3 Miles

Bearing North 21 Chains 21 Links

Road to Mess^rs Macredie

Mr Mc MILLAN'S

R & A MACREDIE

SHEEP HILLS RUN

Bearing North 8° 15' West 4 Miles 42 Chains

Bearing North 6° 15' East 10 Miles 42 Chains

Bearing North 6 Miles 30 Chains

Bearing East 2 Miles

WARRACNABAEL RUN

Chains 2.75 Termination of Boundary between Warracnabael and Kewell Runs

Bearing East 11° 30' North

Old Marked Tree Line

Bearing East 3 Miles

WARAMBEACK CREEK

KEWELL RUN

Road from Hill Station to Clonorchy

Bearing North 45° East 10 Miles 40 Chains

LONGERENONG RUN

PLAN OF

SHEEP HILLS RUN

BOUNDARIES

Note Pegs are placed at the end of every Twenty Chains upon the Boundary Lines, with the exception of those "Bearing East 5 Miles" and "Bearing North 35° West 5 Miles 41 Chains 87 Links" upon which Boundaries Pegs occur at the end of every 10 Chains.
The Boundaries are distinctly marked and all Trees upon the several Lines cut down.

12 11 10 9 8 7 6 5 4 3 2 1 0 ¼ ½ ¾ mile

Surveyor General's Office.
21st April 1856
A.H.

RUN PLAN 403 SHEEP HILLS 21.4.1856

64 R.C. April 21/56